

Number: GZHH00586198

Mar 19, 2025

Date:

Applicant:

FLASHBAY ELECTRONICS BUILDING2, JIXUN INDUSTRIAL PARK, XINJIAO, DONG'AO VILLAGE, SHATIAN TOWN, HUIYANG DISTRICT, HUIZHOU CITY, GUANGDONG PROVINCE, P. R. CHINA

Sample Description:

| One (1) set of submitted sample said to be : | | | |
|--|---|-----------------------------|--|
| Item Name | : | Pen Series | |
| Item No. | : | Radiance (RA) | |
| Country of Origin | : | China | |
| Date Sample Received | : | Mar 04, 2025 & Mar 10, 2025 | |
| Testing Period | : | Mar 04, 2025 ~ Mar 19, 2025 | |

| Tested | Sample |
|--|--|
| GZHH00586198-01 | GZHH00586198-02 |
| | |
| | |
| | æ |
| | |
| | |
| SAMPLE SAMPLE | SAMPLE |
| | NV VII |
| 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 6 | 15 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 6 |
| | 13 40 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 6 |
| *************************************** | *************************************** |

Tests conducted:

As requested by the applicant, refer to attached page(s) for details.

To be continued



Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编: 510730) Tel +8620 28209114 intertek.com.cn intertek.com





. .

Test Report

Number: GZHH00586198

| Tested sample | Standard/Testing Item | <u>Result</u> |
|----------------------|---|---------------|
| Tested components of | EU RoHS Directive 2011/65/EU and its Amendment(s) | Pass |
| submitted sample | including (EU) 2015/863 Article 4(1) on Restricted Substances | |
| • | Content | |
| ******* | *************************************** | ******* |

Authorized by: For Intertek Testing Services Shenzhen Ltd. Guangzhou Branch, Hardlines

A i N

Victor T.J. Wang General Manager



Should you have any query on this report, please click the link below: https://verifyindex.intertek.com.cn/home/index?id=hl_report_verify



Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编: 510730) Tel +8620 28209114 intertek.com.cn intertek.com





Tests Conducted

Number: GZHH00586198

1 <u>EU RoHS Directive 2011/65/EU and its Amendment(s) including (EU) 2015/863 Article 4(1) on Restricted</u> Substances Content

(A) Screening Test by XRF Spectroscopy

Cadmium (Cd), Lead (Pb), Mercury (Hg), Chromium (Cr) and Bromine (Br) content were measured with reference to IEC 62321-3-1 Edition 1.0: 2013by XRF spectroscopy and chemical confirmation test for RoHS restricted substances.

(A) Results:

| Screened Components | | XRF Results | Chemical Confirmation Result |
|------------------------|----|--------------|------------------------------|
| | Cd | ND | |
| | Pb | ND | |
| (1) | Hg | ND | NT |
| | Cr | ND | |
| | Br | ND | |
| | Cd | ND | |
| | Pb | ND | |
| (2) | Hg | ND | NT |
| | Cr | ND | |
| | Br | NT | |
| | Cd | ND | |
| | Pb | ND | |
| (3) | Hg | ND | Cr ⁶⁺ : Negative |
| | Cr | Inconclusive | |
| | Br | NT | |
| | Cd | ND | |
| | Pb | ND | |
| (4) | Hg | ND | NT |
| | Cr | ND | |
| | Br | ND | |
| | Cd | ND | |
| | Pb | ND | |
| (5) | Hg | ND | NT |
| | Cr | ND | |
| | Br | ND | |
| | Cd | ND | |
| | Pb | ND | |
| (6) | Hg | ND | NT |
| | Cr | ND | |
| | Br | ND | |
| | Cd | ND | |
| | Pb | ND | |
| (7) | Hg | ND | NT |
| | Cr | ND | |
| | Br | ND | |



Tel +8620 28209114 intertek.com.cn intertek.com

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. 广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003



Tests Conducted

Number: GZHH00586198

| Screened Components | XRF Results | | Chemical Confirmation Result |
|------------------------|----------------|----------|------------------------------|
| | Cd | ND | |
| | Pb | ND | |
| (8) | Hg | ND | NT |
| | Cr | ND | |
| | Br | ND | |
| | Cd | ND | |
| | Pb | ND | |
| (9) | Hg | ND | NT |
| | Cr | Detected | |
| | Br | NT | |
| | Cd | ND | |
| (1.2) | Pb | ND | |
| (10) | Hg | ND | NT |
| | Cr | ND | |
| | Br | NT | |
| | Cd | ND | |
| | Pb | ND | |
| (11) | Hg | ND | NT |
| | Cr | ND | |
| | Br | ND | |
| | Cd | ND | |
| | Pb | ND | |
| (12) | Hg | ND | NT |
| | Cr | ND | |
| | Br | ND | |
| | Cd | ND | |
| | Pb | ND | |
| (13) | Hg | ND | NT |
| | Cr | ND | |
| | Br | ND | |
| | Cd | ND | |
| | Pb | ND | |
| (14) | Hg | ND | NT |
| | Cr | ND | |
| | Br | NT | |
| | Cd | ND | |
| | Pb | ND | |
| (15a) | Hg Cr | ND | NT |
| | Cr | ND | |
| | Br | ND | |
| | Cd | ND | |
| | Pb | ND | |
| (15b) | (15b) Hg ND NT | NT | |
| | Cr | ND | |
| | Br | ND | |



Tel +8620 28209114 intertek.com.cn intertek.com

深圳天祥质量技术服务有限公司广州分公司

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司 District, Guangzhou, Guangdong, China.



Tests Conducted

Number: GZHH00586198

| Screened Components | XRF Results | | Chemical Confirmation Result |
|------------------------|-------------|--------------|------------------------------|
| | Cd | ND | |
| | Pb | ND | |
| (15c) | Hg | ND | NT |
| | Cr | ND | |
| | Br | ND | |
| | Cd | ND | |
| | Pb | ND | N. |
| (15d) | Hg | ND | NT |
| | Cr | ND | |
| | Br | NT | |
| | Cd | ND | |
| (45) | Pb | ND | |
| (15e) | Hg | ND | NT |
| | Cr | ND | |
| | Br | NT | |
| | Cd | ND | |
| | Pb | ND | |
| (15f) | Hg | ND | NT |
| | Cr | ND | |
| | Br | NT | |
| | Cd | ND | |
| (4.0) | Pb | ND | |
| (16) | Hg | ND | NT |
| | Cr | ND | |
| | Br Cd | ND | |
| | | ND | |
| (17) | Pb | ND | NT |
| (17) | Hg | ND | |
| | Cr | ND ND | |
| | Br Cd | ND ND | |
| | Pb | ND | |
| (18) | Hg | ND | Cr ⁶⁺ : Negative |
| (10) | Cr | Inconclusive | |
| | Br | NT | |
| | Cd | ND | |
| | Pb | ND | |
| (19) | Hg | ND | NT |
| | Cr | ND | |
| | Br | Detected | |
| | Cd | ND | |
| | Pb | ND | |
| (20a) | (20a) PDDS. | PBBs : ND | |
| (200) | Cr | ND | PBDEs : ND |
| | Br | Inconclusive | |



Tel +8620 28209114 intertek.com.cn intertek.com

深圳天祥质量技术服务有限公司广州分公司

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司 District, Guangzhou, Guangdong, China.



Tests Conducted

Number: GZHH00586198

| Screened Components | XRF Results | | Chemical Confirmation Result |
|------------------------|-------------|--------------|------------------------------|
| | Cd | ND | |
| | Pb | ND | |
| (20b) | Hg | ND | NT |
| | Cr | ND | |
| | Br | NT | |
| | Cd | ND | |
| | Pb | ND | PBBs : ND |
| (21) | Hg | ND | PBDEs : See appendix |
| | Cr | ND | |
| | Br | Inconclusive | |

(B) Phthalate Screening Test

| Screened Components | Items | Screened Results(phthalates) | Chemical Confirmation Result |
|------------------------|--------|------------------------------|---------------------------------|
| | DEHP | Р | |
| 1 | BBP | Р | NT |
| I | DBP | Р | INT |
| | DIBP | Р | |
| | DEHP | Р | |
| 4 | BBP | Р | NT |
| 4 | DBP | Р | INT |
| | DIBP | Р | |
| | DEHP | Р | |
| 5 | BBP | Р | NT |
| 5 | DBP | Р | IN I |
| | DIBP | Р | |
| | DEHP | Р | |
| 6 | BBP | Р | NT |
| 0 | DBP | Р | IN I |
| | DIBP P | | |
| | DEHP | Р | |
| 7 | BBP | Р | NT |
| | DBP | Р | IN I |
| | DIBP | Р | |
| | DEHP | Р | |
| 8 | BBP | Р | NT |
| 0 | DBP | Р | IN I |
| | DIBP | Р | |
| | DEHP | Р | |
| 11 | BBP | Р | NT |
| 11 | DBP | Р | IN I |
| | DIBP | Р | |
| | DEHP | Р | |
| 10 | BBP | Р | NIT |
| 12 | DBP | Р | NT |
| | DIBP | Р | |

Page 6 of 13

Tel +8620 28209114 intertek.com.cn intertek.com

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. 广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003



Tests Conducted

| Screened Components | Items | Screened Results(phthalates) | Chemical Confirmation Result |
|------------------------|-------|------------------------------|---------------------------------|
| • | DEHP | Р | |
| 13 | BBP | Р | NT |
| 15 | DBP | Р | INT |
| | DIBP | Р | |
| | DEHP | Р | |
| 15a | BBP | Р | NT |
| 1Ja | DBP | Р | INT |
| | DIBP | Р | |
| | DEHP | Р | |
| 15b | BBP | Р | NT |
| 150 | DBP | Р | INT |
| | DIBP | Р | |
| | DEHP | Р | |
| 15c | BBP | Р | NT |
| 150 | DBP | Р | IN I |
| | DIBP | | |
| | DEHP | Р | |
| 16 | BBP | Р | NT |
| 10 | DBP | Р | |
| | DIBP | Р | |
| | DEHP | Р | |
| 17 | BBP | Р | NT |
| | DBP | Р | INT |
| | DIBP | Р | |
| | DEHP | Р | |
| 19 | BBP | Р | NT |
| 19 | DBP | Р | IN I |
| | DIBP | Р | |
| | DEHP | Р | |
| 20a - | BBP | Р | NT |
| | DBP | Р | IN I |
| | DIBP | Р | |
| | DEHP | Р | |
| 21 | BBP | Р | NT |
| 21 | DBP | Р | IN I |
| | DIBP | Р | |

DBP = Dibutyl phthalate

DEHP = Di-(2-ethyl hexyl) phthalate

BBP = Benzyl butyl phthalate

DIBP = Di-(iso-butyl) phthalate

Detected = Below the lower screening limit of table (C) and pass

ND = Not detected

NT = Not tested

P = Pass



Tel +8620 28209114 intertek.com.cn intertek.com

深圳天祥质量技术服务有限公司广州分公司

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司 District, Guangzhou, Guangdong, China.



Tests Conducted

Negative = A negative test result indicated the concentration of Cr(VI) is less than threshold of 0.1 μ g/cm²

Number:

GZHH00586198

for boiling-water-extraction procedures by UV-VIS Spectrophotometer analysis. The coating is considered a non-Cr(VI) based coating.

Appendix:

| Testing Itom | Result |
|--|--------|
| Testing Item | 21 |
| Polybrominated Biphenyls (PBBs)(mg/kg) | |
| Monobromobiphenyl (MonoBB) | ND |
| Dibromobiphenyl (DiBB) | ND |
| Tribromobiphenyl (TriBB) | ND |
| Tetrabromobiphenyl (TetraBB) | ND |
| Pentabromobiphenyl (PentaBB) | ND |
| Hexabromobiphenyl (HexaBB) | ND |
| Heptabromobiphenyl (HeptaBB) | ND |
| Octabromobiphenyl (OctaBB) | ND |
| Nonabromobiphenyl (NonaBB) | ND |
| Decabromobiphenyl (DecaBB) | ND |
| Polybrominated Diphenyl Ethers (PBDEs)(m | ng/kg) |
| Monobromodiphenyl Ether (MonoBDE) | ND |
| Dibromodiphenyl Ether (DiBDE) | ND |
| Tribromodiphenyl Ether (TriBDE) | ND |
| Tetrabromodiphenyl Ether (TetraBDE) | ND |
| Pentabromodiphenyl Ether (PentaBDE) | ND |
| Hexabromodiphenyl Ether (HexaBDE) | ND |
| Heptabromodiphenyl Ether (HeptaBDE) | ND |
| Octabromodiphenyl Ether (OctaBDE) | ND |
| Nonabromodiphenyl Ether (NonaBDE) | ND |
| Decabromodiphenyl Ether (DecaBDE) | 196 |

(C1) XRF Screening limits in mg/kg for Regulated Elements in Various Matrices

| Element | Polymer Materials | Metallic Materials | Composite Materials |
|---------|-----------------------|------------------------|------------------------|
| Cd | P ≤ 70 < X < 130 ≤ F | P ≤ 70 < X < 130 ≤ F | P ≤ 70 < X < 150 ≤ F |
| Pb | P ≤ 700 < X < 1300≤ F | P ≤ 700 < X < 1300 ≤ F | P ≤ 500< X < 1500 ≤ F |
| Hg | P ≤ 700< X < 1300 ≤ F | P ≤ 700 < X < 1300 ≤ F | P ≤ 500 < X < 1500 ≤ F |
| Cr | P ≤ 700< X | P ≤ 700 < X | P ≤ 500 < X |
| Br | P ≤ 300< X | Not applicable | P ≤ 250 < X |

Tel +8620 28209114 intertek.com.cn intertek.com

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编: 510730) Page 8 of 13





Number: GZHH00586198

Tests Conducted

(C2) Preliminary Screening limits in mg/kg for phthalates test.

| Phthalates | Polymer Materials |
|-------------------------------------|-------------------|
| Dibutyl phthalate (DBP) | P ≤ 600 < X |
| Di-(2-ethyl hexyl) phthalate (DEHP) | P ≤ 600 < X |
| Benzyl butyl phthalate (BBP) | P ≤ 600 < X |
| Di-(iso-butyl) phthalate (DIBP) | P ≤ 600 < X |

P = Pass

X = Inconclusive result

F = Fail

mg/kg = milligram per kilogram = ppm

(D) Estimated Detection Limits in mg/kg for Regulated Elements in Various Matrices

| Element | Polymer Materials | Metallic Materials | Composite Materials |
|---------|-------------------|--------------------|---------------------|
| Cd | 50 | 70 | 70 |
| Pb | 100 | 200 | 200 |
| Hg | 100 | 200 | 200 |
| Cr | 100 | 200 | 200 |
| Br | 200 | Not applicable | 200 |

Disclaimers:

This XRF Screening report is for reference purposes only. The applicant shall make its/his/her own judgment as to whether the information provided in this XRF Screening and Chemical Confirmation Test Report is sufficient for its/his/her purposes.

The results shown in this XRF Screening report will differ based on various factors, including but not limited to, the sample size, thickness, area, surface flatness, equipment parameters and matrix effect (e.g. plastic, rubber, metal, glass, ceramic etc.). Further wet chemical pre-treatment with relevant chemical equipment analysis is required to obtain quantitative data.



深圳天祥质量技术服务有限公司广州分公司

510730)

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司 District, Guangzhou, Guangdong, China. 广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003

房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编:

Tel +8620 28209114 intertek.com.cn intertek.com





Number: GZHH00586198

Tests Conducted

(E) Chemical Test Methods:

| Testing Item | Testing Method | Detection Limit |
|---|--|------------------------|
| Dolybrominated Diphonyl | With reference to IEC 62321-6 Edition 1.0:2015, by solvent extraction and determined by GC/MS and further HPLC confirmation when necessary | 100 mg/kg |
| Chromium (VI) (Cr(VI)) Content | With reference to IEC 62321-7-1 Edition 1.0:2015, by boiling water extraction and determined by UV-VIS Spectrophotometer | 0.1 µg/cm ² |
| Dibutyl phthalate (DBP), Di-(2-ethyl hexyl) phthalate (DEHP), Benzyl butyl phthalate (BBP) and Di-(iso-butyl) phthalate (DIBP) | With reference to IEC 62321-8 Edition 1.0:2017, by Gas Chromatographic-Mass Spectrometric (GC-MS) analysis | 50 mg/kg |

The test methods IEC 62321 series are the designated test methods in EN IEC 63000:2018.

(F) RoHS Requirement:

| Restricted Substances | Limits |
|--|-------------------|
| Cadmium (Cd) | 0.01% (100 mg/kg) |
| Lead (Pb) | 0.1% (1000 mg/kg) |
| Mercury (Hg) | 0.1% (1000 mg/kg) |
| Chromium (VI) (Cr(VI)) | 0.1% (1000 mg/kg) |
| Polybrominated Biphenyls (PBBs) | 0.1% (1000 mg/kg) |
| Polybrominated Diphenyl Ethers (PBDEs) | 0.1% (1000 mg/kg) |
| Dibutyl phthalate (DBP) | 0.1% (1000 mg/kg) |
| Di-(2-ethyl hexyl) phthalate (DEHP) | 0.1% (1000 mg/kg) |
| Benzyl butyl phthalate (BBP) | 0.1% (1000 mg/kg) |
| Di-(iso-butyl) phthalate (DIBP) | 0.1% (1000 mg/kg) |

The limit was quoted according to EU RoHS Directive 2011/65/EU and its Amendment(s) including (EU) 2015/863 Article 4(1) on Restricted Substances Content.



Page 10 of 13

Tel +8620 28209114 intertek.com.cn intertek.com

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. 广州市黄埔区保盈东路 8号 401 房、501 房、601 房、801 房、901 房、1003



Tests Conducted

Tested Components:

| (1) | Coatings (black, white) on metal. | |
|-----|-----------------------------------|--|
|-----|-----------------------------------|--|

- Silver color metal excluding coatings. Silver color metal.
- White woven with inaccessible adhesive.
- Black soft plastic.
- Semi-transparent beige plastic excluding coating.

Number:

GZHH00586198

- (2) (3) (4) (5) (6) (7) (8) Silver color coating on plastic. Dark black soft plastic.
- (9) Light silver color metal.
- (10)Silver color metal.
- White plastic. (11)
- (12) Black ink.
- (13) Semi-transparent plastic.
- (14)Light silver color metal.
- (15)Switch
- (15a) White plastic
- (15b) Grey plastic.
- Black plastic. (15c)
- (15d) Silver color metal
- (15e) Silver/copper color metal
- Black treated metal (15f)
- Silver color plated plastic. (16)
- Matt semi-transparent plastic. (17)
- (18) Silver color metal.
- (19) Light black plastic.
- (20) LĔD
- (20a) Transparent plastic
- (20b) Silver color metal
- (21) Dark grey plastic.



Page 11 of 13

Tel +8620 28209114 intertek.com.cn intertek.com




深圳天祥质量技术服务有限公司广州分公司

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司 District, Guangzhou, Guangdong, China.



Tests Conducted





Page 12 of 13

Tel +8620 28209114 intertek.com.cn intertek.com



深圳天祥质量技术服务有限公司广州分公司

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司 District, Guangzhou, Guangdong, China.



Tests Conducted

Number: GZHH00586198



Remark: The products in the reference photo are not tested in this report. It's declared by the applicant that they are the same series of products with the particular tested sample, just included in the report for reference.

End of report

The statements of conformity reported have considered the decision rule agreed, namely that Intertek have taken account of measurement uncertainty as calculated by Intertek, and applied according to ILAC-G8/09:2019 (Non-binary acceptance based on guard band $\mathbf{w} = \mathbf{U}$) except designation from the customer, regulation or test specification. This decision rule only applies to the numeric test results.

The sample(s) and sample information hereto are provided by the client who shall be solely responsible for the authenticity and integrity thereof. The results shown in this report relate only to the sample(s) tested. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. This report shall not be reproduced unless with prior written approval from Intertek Testing Services Shenzhen Limited, Guangzhou Branch.



Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司 Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编: 510730) Tel +8620 28209114 intertek.com.cn intertek.com

